



NSF International Beverage Quality
Statement of Audit Completion

EUREAU SOURCES SAS

Audit Location

EUREAU SOURCES SAS - Site Marolles 60
Bourneville 60890 Marolles
France

Company is a participant in the audit program
Association Française de l'Industrie des Fontaines à Eau
Bottler

Date of Audit
27-MAR-2017



This page (1 of 1) is a public document; may be displayed and distributed by the above named Corporate; expires one (1) year from the above audit date; and does not indicate NSF certification or registration.

Audit report and scoring grid for watercoolers bottling plants

Rapport d'Audit et grille de score applicable à l'embouteillage de bonbonnes d'eau pour fontaines réfrigérantes



Audit of the company:

Source of:
Date of completion of the audit:
Name of the Auditor:
Society of the Auditor:

Contact details of the auditor (Tel, fax, mail):
Accompanying person (s) of the company audited:

Contact details (Tel, fax, mail):
Objective of the Audit:
Annual visit:

Initial visit:
Special visit:
Date of first audit carried out according to AFIFAE requirements:

Audit de la société :

Source de :
Date de réalisation de l'audit :
Nom de l'Auditeur :
Société de l'Auditeur :

Coordonnées de l'auditeur (Tel, fax, mail) :
Personne(s) accompagnatrice(s) de la société auditée :

Coordonnées de l'accompagnateur (Tel, fax, mail) :
Objectif de l'Audit :
Visite annuelle :

Visite initiale :
Visite spéciale :
Date du premier audit réalisé d'après le référentiel AFIFAE :

Eureau Sources SAS

version du 21/11/16

Clair 'Oise from Marolles

27-Mar-17

Kathy Griffiths
NSF International

kgriffiths@nsf.org.
+44 7768 003711

Jean Cadart
00 33 6 87 97 42
74
jcadart@eureau-sources.com

initial visit
according to
AFIFAE
requirements.

27-Mar-17

Score obtained for bottling plant:

Maximum score applicable:
% Of the obtained score:
Number of failures on 18 critical points (CP): 0

Score obtenu pour les fontaines à bonbonnes :

Score maximum applicable :
% du score obtenu :
Nombre d'échec sur les 18 points critiques (CP) :

	976
	1010
	96.63
	0

Audit validated (yes / no): See page 5 of the audit guide
Action plan to be provided to the auditor for:

Audit validé (oui / non) : Cf. p 5 du guide d'audit
Plan d'action à fournir à l'auditeur pour le :

Audit to be completed with an additional visit (yes/ no):

Audit à compléter par une visite complémentaire (oui/non) : No

Signature of auditor:
K Griffiths

Signature de l'auditeur :
K Griffiths

Signature de l'accompagnateur : / Signature of accompanying person:

Remarques et commentaires généraux / General remarks and comments
This watercooler bottling plant is approximately 75 Km north east of Paris. It opened in 2014 and can bottle at up to 1,000 large bottles an hour. The spring water source is at 60m depth. The ground is sand and gravel with a good deep protective clay layer over the top. There is iron removal from the source water by use of compressed air. The laboratory on site closely monitors the microbiological and chemical parameters of the water and the washed bottles and results seen during the audit appeared consistently very good.