



NSF International Beverage Quality
Statement of Audit Completion


EUREAU SOURCES SAS

Audit Location

EUREAU SOURCES SAS - Site Tessières 15
La Croix Petite 15130 Teissières Les Bouliès
France

Company is a participant in the audit program
Association Française de l'Industrie des Fontaines à Eau
Bottler

Date of Audit
29-MAR-2017



This page (1 of 1) is a public document; may be displayed and distributed by the above named Corporate; expires one (1) year from the above audit date; and does not indicate NSF certification or registration.

Audit report and scoring grid for watercoolers bottling plants

Rapport d'Audit et grille de score applicable à l'embouteillage de bonbonnes d'eau pour fontaines réfrigérantes



Audit of the company:

Source of:
Date of completion of the audit:
Name of the Auditor:
Society of the Auditor:

Contact details of the auditor (Tel, fax, mail):
Accompanying person (s) of the company audited:

Contact details (Tel, fax, mail):
Objective of the Audit:
Annual visit:

Initial visit:
Special visit:
Date of first audit carried out according to AFIFAE requirements:

Audit de la société :

Source de :
Date de réalisation de l'audit :
Nom de l'Auditeur :
Société de l'Auditeur :

Coordonnées de l'auditeur (Tel, fax, mail) :
Personne(s) accompagnatrice(s) de la société auditée :

Coordonnées de l'accompagnateur (Tel, fax, mail) :
Objectif de l'Audit :
Visite annuelle :

Visite initiale :
Visite spéciale :
Date du premier audit réalisé d'après le référentiel AFIFAE :

Eureau Sources SAS
Puy du Soleil at Teissieres

29-Mar-17

Kathy Griffiths
NSF International

version du 21/11/16

kgriffiths@nsf.org.
+44 7768 003711

Jean Cadart
00 33 6 87 97 42
74
jcadart@eureau-sources.com

initial visit
according to
AFIFAE
requirements.

29-Mar-17

Score obtained for bottling plant:

Maximum score applicable:
% Of the obtained score:
Number of failures on 18 critical points (CP): 0

Score obtenu pour les fontaines à bonbonnes :

Score maximum applicable :
% du score obtenu :
Nombre d'échec sur les 18 points critiques (CP) :

1071
1095
97.81
0

Audit validated (yes / no): See page 5 of the audit guide
Action plan to be provided to the auditor for:

Audit validé (oui / non) : Cf. p 5 du guide d'audit
Plan d'action à fournir à l'auditeur pour le :

Audit to be completed with an additional visit (yes/ no):

Audit à compléter par une visite complémentaire (oui / non) : No

Signature of auditor:
K. Griffiths

Signature de l'auditeur :
K. Griffiths

Signature de l'accompagnateur : / Signature of accompanying person:

Remarques et commentaires généraux / General remarks and comments

This watercooler bottling plant opened in 1996 but the source here has been used since 1821. It can bottle at up to 600 large bottles per hour (more commonly at 500-520 bph with the assistance of 3 storage tanks which can hold 60 cubic metres of water between them and fill up overnight). The spring water source is very deep with the borehole in a nearby field being 257m deep. The water travels to the bottling plant by a short PE pipeline and there is Iron, Manganese and Arsenic removal as permitted by law. The laboratory on site closely monitors the microbiological and chemical parameters of the water and the washed bottles and results seen during the audit appeared consistently good.